

ID/Ref: JMX11719

HITACHI

FOB Price: ASK ¥ JPY



Category:	Excavators
Maker:	HITACHI
Model:	ZX225US-3
Serial No:	2159**
Year:	2010
Hour:	7474
Shoe:	N/A
Location:	HAKATA
Machine Link:	https://mail.jamex.co.jp/excavators/hitachi/zx225us-3/machine/11719
Description:	* Oil leak at the bucket cylinder * Play/looseness at the bucket mounting point * A/C malfunction (no cold air)
URL:	