

KOMATSU PC120-8	
MAKER:	KOMATSU
MODEL:	PC120-8
SERIAL NO.:	826**
YEAR:	2010YR
HOUR:	7284Hrs
SPEC:	KOMATSU PC120-8 2010yr 7,284hr
LOCATION:	YOKOHAMA
PLATE NO.:	N/A
STAMP:	N/A

CONDITION

Ref No: JMX11198

Detail	Details
Engine	Grade: C - Engine head cover oil seepage
Radiator	Grade: C
Operation	Grade: C
Swing Device	Grade: C - Swing circle seal coming off
Travel	Grade: C

COMMENTS:

Oil leak from track roller 4 pcs 9 Travel (right) Track Roller C Revolving frame (left) deformed C Revolving frame (right) repair mark Revolving Frame C Track frame (front) deformed C Track frame (left) deformed C Track frame (right) deformed Track Frame C Cab skylight repair mark C Cab door deformed Cab/Canopy C Seat torn C Monitor panel not working Operator's Compartment C Air Conditioner C Hydraulic tank oil seepage C Counterweight deformed Tank/Exterior Cover C Paint C Rusted & corroded machine bod

JAMEX CO., LTD.

English: We are not responsible for the accuracy of this inspection information or the actual condition of the machine.

Japanese: この査定情報の正確性および実際の機械の状態について、当社は責任を負いません。