

KOMATSU PC360LC-11	
MAKER:	KOMATSU
MODEL:	PC360LC-11
SERIAL NO.:	915**
YEAR:	YR
HOUR:	11161Hrs
SPEC:	600G, ROPS CAB, PIPING, A/C
LOCATION:	BUSAN
PLATE NO.:	N/A
STAMP:	N/A

CONDITION

Ref No: JMX11894

Detail	Details
Engine	Grade: C
Radiator	Grade: C
Operation	Grade: C
Swing Device	Grade: C
Travel	Grade: C
Overall Appearance	Grade: E - Crack on cab front glass including lower
Bottom/Reinforce Plate Condition	Grade: D - Crack on right lower side
Bucket Oil Leak from Cylinder	Grade: D - Cylinder rod discolored
Bucket Link Condition	Grade: D - WORN

COMMENTS:

600G, ROPS CAB, PIPING, A/C

JAMEX CO., LTD.

English: We are not responsible for the accuracy of this inspection information or the actual condition of the machine.

Japanese: この査定情報の正確性および実際の機械の状態について、当社は責任を負いません。