

| KOMATSU PC128US-11 |                                              |
|--------------------|----------------------------------------------|
| YEAR:              | 2020YR                                       |
| HOUR:              | 2051Hrs                                      |
| SPEC:              | KOMATSU PC128US-11 2020yr 2,051hrs Available |
| SHOE:              | N/A                                          |
| LOCATION:          | YOKOHAMA                                     |
| PLATE NO.:         | N/A                                          |
| STAMP:             | N/A                                          |

ENGINE

|                          |     |
|--------------------------|-----|
| Maker:                   | N/A |
| Model:                   | N/A |
| S/No.:                   | N/A |
| EXHAUST GAS REGULATIONS: | N/A |

CONDITION

Ref No: JMX8798

| Detail         | Details                                                                           |
|----------------|-----------------------------------------------------------------------------------|
| Engine         | Grade: C - (Oil Leak) Engine bottom oil oozing                                    |
| Radiator       | Grade: C                                                                          |
| Operation      | Grade: C                                                                          |
| Swing Device   | Grade: C                                                                          |
| Travel (left)  | Grade: C - Shoe (steel, roadliner, rubber pad) Rubber pad broken more than 20 pcs |
| Travel (right) | Grade: C - Shoe (steel, roadliner, rubber pad) Rubber pad broken more than 20 pcs |

COMMENTS:

|                         |
|-------------------------|
| No additional comments. |
|-------------------------|

JAMEX CO., LTD.

**English:** This inspection information is for reference only. It is not to guarantee the condition of the actual machine. For more information, visit our website at [www.jamex.co.jp](http://www.jamex.co.jp)

**Japanese:** この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。詳細については、当社ウェブサイト [www.jamex.co.jp](http://www.jamex.co.jp) をご覧ください。

Generated on: 2026-07-22 01:06:36

Machine ID: JMX8798