

| MITSUBISHI FD120NT |                                                                                 |
|--------------------|---------------------------------------------------------------------------------|
| YEAR:              | 2017YR                                                                          |
| HOURL:             | 7102Hrs                                                                         |
| SPEC:              | MITSUBISHI FD120NT Yr 2015 Yr 7102 3m, 12000kg, FORK SHIFT(BY MANUAL), W/HANDLE |
| SHOE:              | N/A                                                                             |
| LOCATION:          | KOBE                                                                            |
| PLATE NO.:         | N/A                                                                             |
| STAMP:             | N/A                                                                             |

ENGINE

|                          |     |
|--------------------------|-----|
| Maker:                   | N/A |
| Model:                   | N/A |
| S/No.:                   | N/A |
| EXHAUST GAS REGULATIONS: | N/A |

CONDITION

Ref No: JMX9996

| Detail                      | Details                                                                                          |
|-----------------------------|--------------------------------------------------------------------------------------------------|
| Engine Radiator             | Grade: C - Unusual noise from the engine: Slight oil leak around the engine (overall).           |
| Operation                   | Grade: C - The warning light comes on.                                                           |
| Travel                      | Grade: C - Foot brake: Not working. Brake oil tank: Oil leak [Moderate].                         |
| Exterior Body               | Grade: C - Steering cylinder oil leak [Slight] Main pump: Oil leak [Slight] Fork Length (1.67 m) |
| Exterior ( under carriage ) | Grade: C - Differential device: Oil leak [Moderate] Transmission: Oil leak [Moderate]            |

COMMENTS:

|                         |
|-------------------------|
| No additional comments. |
|-------------------------|

JAMEX CO., LTD.

**English:** This inspection information is for reference only. It is not to guarantee the condition of the actual machine. For more information, visit our website at [www.jamex.co.jp](http://www.jamex.co.jp)

**Japanese:** この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。詳細については、当社ウェブサイト [www.jamex.co.jp](http://www.jamex.co.jp) をご覧ください。

Generated on: 2026-07-21 23:21:29

Machine ID: JMX9996